



MODEL
2007 XK

DATE
20 June 2006

NUMBER
XK501-003

SERVICE

TECHNICAL BULLETIN

SECTION: 501-14

Smart Key Docking Station Cover Return Spring

AFFECTED VEHICLE RANGE:

New XK

VIN: B04704 to B04753

Model Year: 2007

CONDITION SUMMARY:

SMART KEY DOCKING STATION COVER RETURN SPRING NOT INSTALLED

Situation: This "information only" bulletin has been published to inform dealer personnel that the production vehicles in the VIN range B04704 to B04753 were built without the return spring installed in the Smart Key docking station cover. The docking station cover will need to be opened and closed manually on these vehicles.



NOTE: The lack of a return spring is not considered a fault. Components associated with this situation are not to be replaced under Warranty.

No customer complaints are anticipated regarding this issue.

Action: No action required.

PARTS:

No parts required. Information purposes only.

WARRANTY:

No warranty associated with this bulletin. This bulletin is issued for information purposes only. Normal warranty policy and procedures apply.

NOTE: The information in Technical Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers." If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether the bulletin applies to a specific vehicle.