



XJ range

DATE 10/05

XJ206-05

SERVICE

TECHNICAL BULLETIN

**Brake Disc Replacement –
Vehicles With Less Than 1,000 Miles –
Warranty Policy Change**

MODEL 2006 MY-ON
XJ range
VIN G49701-ON

Issue:

The current policy of replacing brake discs in pairs on the same axle for low time in-service vehicles (with less than 1,000 miles) has now been rescinded. The policy for replacing brake discs under warranty on these vehicles has been revised and is detailed below.

The failed part **only** shall be changed under warranty if **all** the following criteria are met:

- The vehicle has completed less than 1,000 miles (1,600 kilometers).
- Only one brake disc across an axle exhibits the fault.
- The part number of the replacement disc is identical to that being removed.

Action:

Effective immediately, observe the above points when replacing brake discs under warranty.

1. For additional information, refer to Global Technical Reference (GTR) XJ Range Workshop Manual Section 206-03, Front Disc Brake or 206-04, Rear Disc Brake.

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY “DO-IT-YOURSELFERS.” DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR DEALER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.



Global Technical Reference (GTR) Workshop Manual Information:

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

Parts Information:

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
326mm Front brake disc (single disc)	C2C 25336 S *	1
355mm Front brake disc (single disc)	C2C 25337 S *	1
Rear brake disc (single disc)	C2C 25339 S *	1

***Note:** The "S" suffix indicates that the part number is for a single disc, since previously these brake discs were only available in sets of two.