



X-TYPE

DATE 09/04

XT308-04

SERVICE

## TECHNICAL BULLETIN

### Transmission Whine – Sound Transmitted By Shift Cables – Revised Shift Cables Available

MODEL 2002 MY-ON  
X-TYPE  
VIN w/ man. trans.  
C00001-ON

**Issue:**

Some X-TYPE vehicles may exhibit a transmission whine (noise) emanating from the transmission. The whine can be transmitted along the gearshift cables into the cabin. A set of revised shift cables has been released to address this concern.

**Action:**

In case of a customer complaint of the above condition, install a set of revised shift cables as outlined below.

**Note:** This Technical Bulletin **MUST** be carried out and the vehicle retested **before** replacing a transmission for this complaint.

#### WORKSHOP PROCEDURE

1. Install a revised gearshift cable set (see Workshop Manual, section: 308-06, SRO 37.16.45).

NOTE: THE INFORMATION IN TECHNICAL BULLETINS IS INTENDED FOR USE BY TRAINED, PROFESSIONAL TECHNICIANS WITH THE KNOWLEDGE, TOOLS, AND EQUIPMENT TO DO THE JOB PROPERLY AND SAFELY. IT INFORMS THESE TECHNICIANS OF CONDITIONS THAT MAY OCCUR ON SOME VEHICLES, OR PROVIDES INFORMATION THAT COULD ASSIST IN PROPER VEHICLE SERVICE. THE PROCEDURES SHOULD NOT BE PERFORMED BY "DO-IT-YOURSELFERS." DO NOT ASSUME THAT A CONDITION DESCRIBED AFFECTS YOUR CAR. CONTACT A JAGUAR RETAILER TO DETERMINE WHETHER THE BULLETIN APPLIES TO YOUR VEHICLE.

**Global Technical Reference (GTR) Workshop Manual Information:**

Dealer access: <https://hub.franchise.jaguar.com>

Internet access: <http://www.jaguartechno.com>

**Parts Information:**

<u>DESCRIPTION</u>	<u>PART NUMBER</u>	<u>QTY</u>
Gearshift cables	C2S 33004	1

**Warranty Information:**

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/miscellaneous expense codes as listed.

Description	SRO	Time	Causal Part Number
Install new gearshift cables	37.16.45	1.2 hrs.	C2S 33004