



X-TYPE

DATE 05/02
Amended 03/03

XT419-S920

SERVICE

TECHNICAL BULLETIN

General Electronic Control Module (GECM) –
Replace –
Service Action S 920

MODEL 2002 MY
X-TYPE
VIN C00344-C25928

Remove and destroy Bulletin XT419-S920 dated 05/02.
Replace with this Bulletin.
This Service Action is superseded by Recall R935.

Issue:

The General Electronic Control Module (GECM) installed in some X-TYPE vehicles (within the above VIN range) may experience an internal circuit failure. This condition could lead to intermittent operation of some electrical systems.

Action:

Refer to Recall R935 described in Technical Bulletin **XT413-R935** dated 03/03.